

25X1A

DISPATCH NO. [REDACTED]
 PAGE 2 OF 4
 DATE:

TO : Chief of Supply Depot
 FROM : Headquarters
 SUBJECT : Pratt & Whitney's Initial Priced Spares List

1. Attached is one (1) copy of P & W's initial Priced Spares List. An additional copy will be sent to you at the time it is incorporated into the contract. For your information, the Maintenance and O/H factors set forth in the list are percentages and quantities are arrived at as shown in the example as follows:

<u>Maintenance</u> <u>Factor</u>	x	<u>Maintenance</u> <u>Periods</u>	x	<u>Units Per</u> <u>Engine</u>	=	<u>Quantity</u>
10%		24		4		9.6

(The machine would automatically round the quantity off to the nearest whole number; in this case, 10)

2. Because of machine limitations, it is necessary to split the list in two parts. The first half contains maintenance spares and the latter half the overhaul parts.

3. The number of maintenance periods and overhaul cycles is set forth on the second page of the Exhibit. If you have any questions, please do not hesitate to give me a call.

25X1A

SIGNED

[REDACTED]

ENCLOSURE:

P & W's Suggested Spare Parts List

CS/DPD-DD/P: [REDACTED]

Distribution:

Orig - [REDACTED]

2 - CS/DPD TT-1002 Spares Folder
 3 - MAT/DPD
 4 - RI/DPD

25X1A

25X1A